Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 4076597 Wo#: 1 Priority: 1 Radio #: 2002 Wtr/Swr: W WO Stat: UNA WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: MRQST

Prob Cd / Primary Ind: MRQST Y Fld Bk Pg/Grid: J18S

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: Service Area: 9

4641 MAX DR SD X St: ES Srvc Area: SE

Intersec: Plt Srve Area: AL

SR Loc: REPLACE BROKEN MTR COVER/LID Init ASN Dt:

Job Desc: PER GET IT DONE APP; REPLACE BROKEN MTR LID; PLS CALL CUST Curr ASN Dt:

WO Loc: WO Gen Dt: 03/21/17 16:0

Facility Tag: WO Type:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643295 Requestr: [redacted] Ph#: [redacted]

Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

786 ST 00/00/00 00:00 End 00/00/00 00:00 JO CC WBS IO Emp Hrs

WO Comments: Page 1 of 1

Creation Dt/Tm:

Last Upd Dt/ID:

Completed by Radio #: Cancel: Total Crew Hours:

New WO

Create

Referral WO

Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 8/28/17 1:21 Last Update ID: DSZ Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: Completed By: WO Generated By: Q4O Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

| SR # | Creation Dt/Tm | Last Update Dt / ID | |
|---|---|---|---|
| 4076597 | 03/21/17 18:03 | 03/21/17 18:03 | Q4O |

**SR Comments**

RPTD VIA GET IT DONE APP

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 4082061 Wo#: 1 Priority: 1 Radio #: 1938 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: MRQST

Prob Cd / Primary Ind: MRQST Y

Fld Bk Pg/Grid: J18S

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 1970 STEPHEN PALMER Service Area: 9

4632 MAX DR SD X St: ES Srvc Area: SE

Intersec: Plt Srve Area: AL

SR Loc: BROKEN COVER MTR Init ASN Dt: 04/17/17 10:28

Job Desc: BROKEN COVER MTR Curr ASN Dt: 04/17/17 10:28

WO Loc: WO Gen Dt: 04/17/17 10:2

Facility Tag: WO Type:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643293 Requestr: [redacted] Ph#: [redacted]

Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

786 RMBL ST 04/17/17 11:45 End 04/17/17 12:00 JO CC WBS IO 1300019 Emp 1 Hrs 0.30

WO Comments: Page 1 of 1 RPL SMALL METAL MTR LID

Creation Dt/Tm: 4/19/17 6:57

Last Upd Dt/ID: 4/19/17 6:57 G2W

Completed by Radio #: Cancel: Total Crew Hours: 0.25

New WO

Create

Referral WO

Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 4/19/17 6:57 Last Update ID: G2W Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 4/19/17 6:57 Completed By: G2W WO Generated By: AOZ Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

| SR # | Creation Dt/Tm | Last Update Dt / ID | |
|---|---|---|---|
| 4082061 | 04/17/17 11:36 | 04/17/17 11:37 | AA9 |

**SR Comments**

PER 1938 RPLCD SMLL METAL MTR LID



| | | | |
|---|---|---|---|
| 4082061 | 04/17/17 10:23 | 04/17/17 10:23 | AA9 |

**SR Comments**

PGDF 1938



| | | | |
|---|---|---|---|
| 4082061 | 04/17/17 10:21 | 04/17/17 10:21 | AOZ |

**SR Comments**

GET IT DONE APP-COVER PLATE BROKEN ON WATER METER COVER. DANGEROUS TRIP HAZARD. NEEDS TO BE REPAIED, NOT JUST MARKED AS IT HAS BEEN FOR MONTHS.

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 4085514 Wo#: 1 Priority: 1 Radio #: 1933 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: 1161

Prob Cd / Primary Ind: 1161 Y Fld Bk Pg/Grid: J18S

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 1970 STEPHEN PALMER Service Area: 9

4606 MAX DR SD X St: ES Srvc Area: SE

Intersec: Plt Srve Area: AL

SR Loc: WTR COMING FROM SIDEWALK Init ASN Dt: 04/27/17 18:5

Job Desc: WTR COMING FROM SIDEWALK Curr ASN Dt: 04/27/17 18:5

WO Gen Dt: 04/27/17 18:5

WO Loc: WO Type:

Facility Tag:

Special Inst: ENVIRONMENTALLY SENSITIVE AREA. PERMITS MAY BE REQUIRED. CONTACT YOUR SUPERVISOR FOR INSTRUCTIONS.

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643288 Requestr: [redacted] Ph#: [redacted]

| Work Cd | Action Cd |
|---|---|
| ESINV | INV |

SR Comments | Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

ST 04/27/17 19:30 End 04/27/17 19:33 JO CC WBS IO 1300019 Emp 1 Hrs 0.10

WO Comments: Page 1 of 1

Creation Dt/Tm: 4/28/17 10:03

Last Upd Dt/ID: 4/28/17 10:03 G2W

SEE WO# 2

Total Crew Hours: 0.05

Completed by Radio #: Cancel:

New WO

Create

Referral WO

Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 4/28/17 10:03 Last Update ID: G2W Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 4/28/17 10:03 Completed By: G2W WO Generated By: KSX Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 4085514 Wo#: 2 Priority: 2 Radio #: 1933 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: 1161

Prob Cd / Primary Ind: 1161 Y

Fld Bk Pg/Grid: J18S

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 1970 STEPHEN PALMER Service Area: 9

4606 MAX DR SD X St: ES Srvc Area: SE

Intersec: Plt Srve Area: AL

SR Loc: WTR COMING FROM SIDEWALK Init ASN Dt:

Job Desc: Curr ASN Dt:

WO Loc: WO Gen Dt: 04/28/17 10:0

Facility Tag: WO Type:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643288 Requestr: [redacted] Ph#: [redacted]

Work Cd Action Cd | SR Comments | Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

ESINV RPL63 ST 04/27/17 19:30 End 04/27/17 20:00 JO CC WBS IO 1300019 Emp 1 Hrs 0.50

WO Comments: Page 1 of 1

Creation Dt/Tm: 4/28/17 10:04

Last Upd Dt/ID: 4/28/17 10:04 G2W

RPL 1" C/S GASKET - MTR 93010612

Completed by Radio #: Cancel: Total Crew Hours: 0.50

New WO

Create

Referral WO

Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 4/28/17 10:04 Last Update ID: G2W Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 4/28/17 10:04 Completed By: G2W WO Generated By: G2W Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 3708564 Wo#: 1 Priority: 3 Radio #: 3003 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO

Prob Cd / Primary Ind: AMIRO Y Fld Bk Pg/Grid: J18S 2

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 3000 PROJECT AMI Service Area:

4593 MONROE AV SD X St: ES Srvc Area:

Intersec: Plt Srve Area:

SR Loc: E08-0104 Init ASN Dt: 02/15/18 09:31

Job Desc: AMI Roll Out Curr ASN Dt: 02/15/18 09:31

WO Loc: WO Gen Dt: 06/23/15 16:3

Facility Tag: WO Type:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643368 Requestr: Ph#: -

Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

AMIRP RPL ST 02/21/18 11:10 End 02/21/18 11:45 JO CC WBS S17008.06.03 IO Emp 1 Hrs 0.60

WO Comments: Page 1 of 1 RPL MTR, 36 POLY OK / CON

Creation Dt/Tm: 2/23/18 14:19

Last Upd Dt/ID: 2/23/18 14:19 DVR

Completed by Radio #: Cancel: Total Crew Hours: 0.58

New WO

Create

Referral WO

Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 2/23/18 14:19 Last Update ID: DVR Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 2/23/18 14:19 Completed By: DVR WO Generated By: DSZ Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Install/Remove/Replace Meter WorkSheet SR: 3708564 WO: 1

Facility Information Sheet Meter

Meter Fac #: 643368

Serial #: 17130211 CIS Act#: 08 - 36822 - 010

Metr Type: DOM

Size: 57

Billing Period : 2 Meter Route: 0

Install Date: 02/21/2018 Ownership: SD Division: 1640 Make: 2

Style: 5

Install Location: M Field Bk: 18S / 2 Thms Bros Pg: 1269J4

Address: 4593 MONROE AV Unit #:

Location Descrip:

Comments:

## Meter Install / Replace reading

| Old Meter | | | | New Meter | | | |
|---|---|---|---|---|---|---|---|
| Serial # | Size | Make | Style | Serial # | Size | Make | Style |
| 96322646 | 02 | 0 | 5 | 17130211 | 57 | 2 | 5 |

| Old Reading | M/B | New Reading |
|---|---|---|
| 1143 | N | 0 |

## Removal Readings

| Reg# | M/B | Removal Read |
|---|---|---|
| | | |
| | | |
| | | |

## ERT Install / Replace

| Reg # | Old ERT# | New ERT# | Make | Style |
|---|---|---|---|---|
| 1 | | | | |

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 3708571 Wo#: 1 Priority: 3 Radio #: 3007 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO

Prob Cd / Primary Ind: AMIRO Y

Fld Bk Pg/Grid: J18S 2

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 3000 PROJECT AMI Service Area:

4651 MONROE AV SD X St: ES Srvc Area:

Intersec: Plt Srve Area:

SR Loc: E08-0104 Init ASN Dt: 02/15/18 09:36

Job Desc: AMI Roll Out Curr ASN Dt: 02/15/18 09:36

WO Gen Dt: 06/23/15 16:3

WO Loc: WO Type:

Facility Tag:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643381 Requestr: Ph#: -

Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

AMIRP RPL ST 02/21/18 10:30 End 02/21/18 11:05 JO CC WBS S17008.06.03 IO Emp 1 Hrs 0.60

WO Comments: Page 1 of 1

Creation Dt/Tm: 2/23/18 14:26

Last Upd Dt/ID: 2/23/18 14:26 DVR

RPL METER, 37 CONCRETE BOX IN DIRT

Total Crew Hours: 0.58

Completed by Radio #: Cancel:

New WO

Create

Referral WO


Priority: Ref to Radio: Work Cd: Fac Type: Fac:


Job Desc:

Last Update Dt: 2/23/18 14:26 Last Update ID: DVR Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 2/23/18 14:26 Completed By: DVR WO Generated By: DSZ Supvr Appv/Rej, Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Install/Remove/Replace Meter WorkSheet SR: 3708571 WO: 1
Facility Information Sheet Meter
Meter Fac #: 643381
Serial #: 16513279
CIS Acct#: 08 - 36835 - 010
Metr Type: DOM
Size: 76
Billing Period : 2
Meter Route: 0
Install Date: 02/21/2018
Ownership: SD
Division: 1640
Make: 2
Style: 5
Install Location: M
Field Bk: J18S / 2
Thms Bros Pg: 1269J4
Address: 4651 MONROE AV
Unit #:
Location Descrip:
Comments:
Meter Install / Replace reading
Old Meter
Serial # Size Make Style
88805691 21 2 5
Old Reading M/B
3968 N
New Meter
Serial # Size Make Style
16513279 76 2 5
New Reading
0
Removal Readings
Reg# M/B Removal Read
ERT Install / Replace
Reg # Old ERT# New ERT# Make Style
1


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Work Order
SR #: 3708536 Wo#: 1 Priority: 3 Radio #: 3007 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO
Prob Cd / Primary Ind: AMIRO Y
Fld Bk Pg/Grid: J18S 2
CIP Proj Name:
Drwg Sheet Itm
Thom Bros Pg: 1269J4
Service Area:
ES Srvc Area:
Plt Srve Area:
Street # Frac Dir Street Name Sfx Suite# Juris
Data Steward: 3000 PROJECT AMI
4539 MAX DR SD
X St:
Intersec:
SR Loc: E08-0104
Job Desc: AMI Roll Out
WO Loc:
Facility Tag:
Special Inst:
Init ASN Dt: 02/13/18 09:36
Curr ASN Dt: 02/13/18 09:36
WO Gen Dt: 06/23/15 16:3
WO Type:
USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643282 Requestr: Ph#:
Work Cd Action Cd
AMIRP RPL
SR Comments
Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00
ST 02/14/18 12:40 End 02/14/18 13:05 JO CC WBS S17008.06.03 IO Emp 1 Hrs 0.40
WO Comments: Page 1 of 1
Creation Dt/Tm: 2/16/18 12:38
Last Upd Dt/ID: 2/16/18 12:38 DVR
RPL METER, 36 CONCRETE BOX IN CONCRETE - WORK ORDER 2 REFERRED TO RADIO # 2002
Total Crew Hours: 0.42
Completed by Radio #:
Cancel:
New WO
Create
Referral WO
Priority: Ref to Radio: Work Cd: Fac Type: Fac:
Job Desc:
Last Update Dt: 2/16/18 12:38 Last Update ID: DVR Last Batch Update Dt: 2/17/18 0:28 Last Batch Update ID: U97SRCLN
WO Completed Dt: 2/16/18 12:38 Completed By: DVR WO Generated By: DSZ Supvr Appv/Rej. Dt:
Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 3708536 Wo#: 2 Priority: 2 Radio #: 2002 Wtr/Swr: W WO Stat: UNA WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO

Prob Cd / Primary Ind: AMIRO Y

Fld Bk Pg/Grid: J18S 2

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: Service Area:

4539 MAX DR SD X St: ES Srvc Area:

Intersec: Plt Srve Area:

SR Loc: E08-0104 Init ASN Dt:

Job Desc: TRIP HAZARD RPL WITH 37 BOX Curr ASN Dt:

WO Loc: WO Gen Dt: 02/16/18 12:3

Facility Tag: WO Type:

Special Inst: ENVIRONMENTALLY SENSITIVE AREA. PERMITS MAY BE REQUIRED. CONTACT YOUR SUPERVISOR FOR INSTRUCTIONS.

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643282 Requestr: Ph#: -

Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

787 ST 00/00/00 00:00 End 00/00/00 00:00 JO CC WBS IO Emp Hrs

WO Comments: Page 1 of 1

Creation Dt/Tm:

Last Upd Dt/ID:

Total Crew Hours:

Completed by Radio #: Cancel:

New WO

Create

Referral WO


Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 2/16/18 12:38 Last Update ID: DVR Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: Completed By: WO Generated By: DVR Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Work Order
SR #: 3985093 Wo#: 1 Priority: 3 Radio #: 3003 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO
Prob Cd / Primary Ind: AMIRO Y
Fld Bk Pg/Grid: J18S 2
Thom Bros Pg: 1269J4
CIP Proj Name:
Drwg Sheet Itm
Service Area: 9
Street # Frac Dir Street Name Sfx Suite# Juris
Data Steward: 3000 PROJECT AMI
4560 MONROE AV SD X St:
ES Srvc Area:
Plt Srve Area:
Intersec:
Init ASN Dt: 02/15/18 09:31
SR Loc: E08-0104
Curr ASN Dt: 02/15/18 09:31
Job Desc: AMI Roll Out
WO Gen Dt: 11/01/16 11:07
WO Type:
WO Loc:
Facility Tag:
Special Inst:
USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643359 Requestr: Ph#:
Work Cd Action Cd
AMIRP RPL
SR Comments
Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00
ST 02/21/18 09:20 End 02/21/18 09:40 JO CC WBS S17008.06.03 IO Emp 1 Hrs 0.30
WO Comments: Page 1 of 1
Creation Dt/Tm: 2/26/18 9:30
Last Upd Dt/ID: 2/26/18 9:30 DVR
RPL MTR, 36 MET OK / DIRT
Total Crew Hours: 0.33
Completed by Radio #:
Cancel:
New WO
Create
Referral WO
Priority: Ref to Radio: Work Cd: Fac Type: Fac:
Job Desc:
Last Update Dt: 2/26/18 9:30 Last Update ID: DVR Last Batch Update Dt: Last Batch Update ID:
WO Completed Dt: 2/26/18 9:30 Completed By: DVR WO Generated By: DSZ Supvr Appv/Rej. Dt:
Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS Info Sht), F9(Wk Sht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Install/Remove/Replace Meter WorkSheet SR: 3985093 WO: 1

Facility Information Sheet Meter

Meter Fac #: 643359

Serial #: 17130214 CIS Act#: 08 - 36813 - 010

Metr Type: DOM

Size: 57

Billing Period: 2 Meter Route: 0

Install Date: 02/21/2018 Ownership: SD Division: 1640 Make: 2

Style: 5

Install Location: M Field Bk: J18S / 2 Thms Bros Pg: 1269J4

Address: 4560 MONROE AV Unit #:

Location Descrip:

Comments:

## Meter Install / Replace reading

| Old Meter | | | | New Meter | | | |
|---|---|---|---|---|---|---|---|
| Serial # | Size | Make | Style | Serial # | Size | Make | Style |
| 99578891 | 02 | 0 | 5 | 17130214 | 57 | 2 | 5 |


| Old Reading | M/B | New Reading |
|---|---|---|
| 1508 | N | 0 |


## Removal Readings


| Reg# | M/B | Removal Read |
|---|---|---|
| | | |
| | | |
| | | |

## ERT Install / Replace

| Reg # | Old ERT# | New ERT# | Make | Style |
|---|---|---|---|---|
| 1 | | | | |


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Work Order
SR #: 3985094 Wo#: 1 Priority: 3 Radio #: 3007 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO
Prob Cd / Primary Ind: AMIRO Y
Fld Bk Pg/Grid: J18S 2
Thom Bros Pg: 1269J4
CIP Proj Name: Drwg Sheet Itm
Service Area: 9
Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 3000 PROJECT AMI
4561 MONROE AV SD X St:
ES Srvc Area:
Plt Srve Area:
Intersec:
Init ASN Dt: 02/15/18 09:3
SR Loc: E08-0104
Curr ASN Dt: 02/15/18 09:3
Job Desc: AMI Roll Out
WO Gen Dt: 11/01/16 11:0
WO Type:
WO Loc:
Facility Tag:
Special Inst:
USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643360 Requestr: Ph#:
Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00
INV INV
ST 02/16/18 08:00 End 02/16/18 08:10 JO CC WBS IO 1300001 Emp 1 Hrs 0.20
WO Comments: Page 1 of 1
Creation Dt/Tm: 2/21/18 13:43
Last Upd Dt/ID: 2/21/18 13:43 VGG
CAR PARKED IN FRONT OF METER BOX NO PARKING / #37 CONCRETE OK / IN DIRT . - WORK ORDER 2 REFERRED TO RADIO # 3970
Total Crew Hours: 0.17
Completed by Radio #:
Cancel:
New WO
Create
Referral WO
Priority: Ref to Radio: Work Cd: Fac Type: Fac:
Job Desc:
Last Update Dt: 2/21/18 13:43 Last Update ID: VGG Last Batch Update Dt: 2/22/18 0:44 Last Batch Update ID: U97SRCLN
WO Completed Dt: 2/21/18 13:43 Completed By: VGG WO Generated By: DSZ Supvr Appv/Rej. Dt:
Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Work Order
SR #: 3985094 Wo#: 2 Priority: 2 Radio #: 3970 Wtr/Swr: W WO Stat: UNA WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: AMIRO
Prob Cd / Primary Ind: AMIRO Y
Fld Bk Pg/Grid: J18S 2
CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4
Street # Frac Dir Street Name Stx Suite# Juris Data Steward: Service Area: 9
4561 MONROE AV SD X St: ES Srvc Area:
Intersec: Plt Srve Area:
SR Loc: E08-0104 Init ASN Dt:
Job Desc: CAR PARKED IN FRONT OF METER BOX. Curr ASN Dt:
WO Gen Dt: 02/21/18 13:4
WO Type:
WO Loc:
Facility Tag:
Special Inst:
USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643360 Requestr: Ph#:
Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00
INV ST 00/00/00 00:00 End 00/00/00 00:00 JO CC WBS IO Emp Hrs
WO Comments: Page 1 of 1
Creation Dt/Tm:
Last Upd Dt/ID:
Total Crew Hours:
Completed by Radio #: Cancel:
New WO
Create
Referral WO
Priority: Ref to Radio: Work Cd: Fac Type: Fac:
Job Desc:
Last Update Dt: 2/21/18 13:43 Last Update ID: VGG Last Batch Update Dt: Last Batch Update ID:
WO Completed Dt: Completed By: WO Generated By: VGG Supvr Appv/Rej. Dt:
Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS Info Sht), F9(Wk Sht), F12(Close)


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Work Order
SR #: 4170846 Wo#: 1 Priority: 3 Radio #: 1528 Wtr/Swr: W WO Stat: UNA WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: SPROJ
Prob Cd / Primary Ind: SPROJ Y
Fld Bk Pg/Grid: J18S 2
CIP Proj Name:
Drwg Sheet Itm
Thom Bros Pg: 1289J4
Service Area: 9
Street # Frac Dir Street Name Sfx Suite# Juris
Data Steward:
4620 MAX DR SD X St:
ES Srvc Area:
Plt Srve Area:
Intersec:
Init ASN Dt:
SR Loc:
Curr ASN Dt:
Job Desc:
WO Gen Dt: 03/01/18 13:3
WO Type:
WO Loc:
Facility Tag:
Special Inst:
USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643290 Requestr: TOM/MIKE Ph#:
Work Cd Action Cd
SR Comments
Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00
INV
ST 00/00/00 00:00 End 00/00/00 00:00 JO CC WBS IO Emp Hrs
WO Comments: Page 1 of 1
Creation Dt/Tm:
Last Upd Dt/ID:
Completed by Radio #:
Cancel:
Total Crew Hours:
New WO
Create
Referral WO
Priority: Ref to Radio: Work Cd: Fac Type: Fac:
Job Desc:
Last Update Dt: 3/6/18 13:00
Last Update ID: FNF
Last Batch Update Dt:
Last Batch Update ID:
WO Completed Dt:
Completed By:
WO Generated By: OSZ
Supvr Appv/Rej. Dt:
Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 4174033 Wo#: 1 Priority: 3 Radio #: 2002 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: SPROJ

Prob Cd / Primary Ind: SPROJ Y Fld Bk Pg/Grid: J18S 2

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 1640 JIMMY EVANS Service Area: 9

4620 MAX DR SD X St: ES Srvc Area:

Intersec: Plt Srve Area:

SR Loc: Init ASN Dt: 03/06/18 16:31

Job Desc: Curr ASN Dt: 03/06/18 16:31

WO Gen Dt: 03/06/18 13:4

WO Loc: WO Type:

Facility Tag:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643290 Requestr: TOM Ph#: -

Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

INV INV ST 03/07/18 18:35 End 03/07/18 18:40 JO CC WBS IO 1300001 Emp 1 Hrs 0.10

WO Comments: Page 1 of 1

Creation Dt/Tm: 3/9/18 6:27

Last Upd Dt/ID: 3/9/18 6:27 TUM

S/N # 17130154
METER READ 0000

Completed by Radio #: Cancel: Total Crew Hours: 0.08

New WO

Create

Referral WO

Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 3/9/18 6:27 Last Update ID: TUM Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 3/9/18 6:27 Completed By: TUM WO Generated By: DSZ Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

Sewer/Water Infrastructure Management

File Edit Actions Window Help

Work Order

SR #: 4174082 Wo#: 1 Priority: 3 Radio #: 2002 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: SPROJ

Prob Cd / Primary Ind: SPROJ Y Fld Bk Pg/Grid: J18S 2

CIP Proj Name: Drwg Sheet Itm Thom Bros Pg: 1269J4

Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 1640 JIMMY EVANS Service Area: 9

4560 MONROE AV SD X St: ES Srvc Area:

Intersec: Plt Srve Area:

SR Loc: Init ASN Dt: 03/06/18 16:15

Job Desc: Curr ASN Dt: 03/06/18 16:15

WO Loc: WO Gen Dt: 03/06/18 13:4

Facility Tag: WO Type:

Special Inst:

USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643359 Requestr: TOM Ph#: -

Work Cd Action Cd | SR Comments | Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00

INV INV ST 03/07/18 18:25 End 03/07/18 18:30 JO CC WBS IO 1300001 Emp 1 Hrs 0.10

WO Comments: Page 1 of 1

Creation Dt/Tm: 3/9/18 6:26

Last Upd Dt/ID: 3/9/18 6:26 TUM

S/N # 17130214
METER READ 0000

Completed by Radio #: Cancel: Total Crew Hours: 0.08

New WO

Create

Referral WO


Priority: Ref to Radio: Work Cd: Fac Type: Fac:

Job Desc:

Last Update Dt: 3/9/18 6:26 Last Update ID: TUM Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 3/9/18 6:26 Completed By: TUM WO Generated By: DSZ Supvr Appv/Rej. Dt:

Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)


Sewer/Water Infrastructure Management
File Edit Actions Window Help
Work Order
SR #: 4174083 Wo#: 1 Priority: 3 Radio #: 2002 Wtr/Swr: W WO Stat: CMP WO Recd Dt: 00/00/00 00:00 Orig Prob Cd: SPROJ
Prob Cd / Primary Ind: SPROJ Y
Fld Bk Pg/Grid: J18S 2
CIP Proj Name: Drwg Sheet Itm
Thom Bros Pg: 1269J4
Service Area: 9
Street # Frac Dir Street Name Sfx Suite# Juris Data Steward: 1640 JIMMY EVANS
4593 MONROE AV SD X St:
ES Srvc Area:
Plt Srve Area:
Intersec:
SR Loc:
Job Desc:
WO Loc:
Facility Tag:
Special Inst:
Init ASN Dt: 03/06/18 16:15
Curr ASN Dt: 03/06/18 16:15
WO Gen Dt: 03/06/18 13:47
WO Type:
USA#: Exp Dt: Fac Typ: METR Fac Seq#: 643368 Requestr: TOM Ph#:
Work Cd Action Cd SR Comments Shutdown Dt: 00/00/00 00:00 Recharge Dt: 00/00/00 00:00
INV INV
ST 03/07/18 18:30 End 03/07/18 18:35 JO CC WBS IO 1300001 Emp 1 Hrs 0.10
WO Comments: Page 1 of 1
Creation Dt/Tm: 3/9/18 6:26
Last Upd Dt/ID: 3/9/18 6:26 TUM
S/N # 17130211
METER READ 0001
Completed by Radio #: Cancel:
Total Crew Hours: 0.08
New WO
Create
Referral WO
Priority: Ref to Radio: Work Cd: Fac Type: Fac:
Job Desc:
Last Update Dt: 3/9/18 6:26 Last Update ID: TUM Last Batch Update Dt: Last Batch Update ID:
WO Completed Dt: 3/9/18 6:26 Completed By: TUM WO Generated By: DSZ Supvr Appv/Rej. Dt:
Enter(Retrieve), F1(Save), F2(Next), F3(Back), F4(Print), F6(Fac), F8(IOS InfoSht), F9(WkSht), F12(Close)

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200083427**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | | |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Request Date:** | Feb 23, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic start date:** | Sep 7, 2018 |
| **Maint. Plan:** | | **Reported By:** | | **Basic finish date:** | Sep 19, 2018 |
| **Address:** | 4609 MONROE AVE,SAN DIEGO,CA -92115-3120,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** RPL WITH 36 POLY LID

**WO Description: (Long text)**

RPL WITH 36 POLY LID

03/11/2018 01:00:57 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

RPL WITH 36 POLY LID

02/23/2018 14:43:00 PST USER RFC_PE5_100 (RFC_PE5_100)

Begin Of Address: 8101224789

4609, MONROE AVE

SAN DIEGO, CA 92115-3120, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101224789 - 4609 MONROE AVE | | |
| **Equipment:** | 1000471235 - 3/4"X7" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643373 | **Notification#:** | 40200178635 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200083427 |
|---|---|---|---|

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000471235 | 3/4"X7" BADGER HR-E DOMESTIC | 8101224789 | 4609 MONROE AVE |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | RPL WITH 36 POLY LID<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-22 10:42:01 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-22 10:45:20 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-22 10:47:23 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1532934 | D7625-16501234(1) | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200178635 | UC | 4609 MONROE AVE,SAN DIEGO,CA -92115-3120,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000471235 | 8101224789 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X7" BADGER | 4609 MONROE AVE | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643373 | 643373 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-BAMI - WCM Meter Boxes for AMI |

**Notification Description (Short Text)**

RPL WITH 36 POLY LID

**Room**

**Notification Description (Long Text)**

03/11/2018 01:00:57 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

RPL WITH 36 POLY LID

02/23/2018 14:43:00 PST USER RFC_PE5_100 (RFC_PE5_100)

---

09/22/2018 11:40:41 PST Jonte Cunningham (JLCUNNINGHAM)

36 poly lid didn't fit 36 concrete box w/metal lid in dirt

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200178635 | UC | 4609 MONROE AVE,SAN DIEGO,CA -92115-3120,US |

| Problem | Object | Activity | Note |
|---|---|---|---|
| REPL BOX/LID #36 | METER BOX - IN DIRT | | |

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200028240**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL PCNF MANC MOBI NMAT PRC SETC/CMPL | **Request Date:** | May 7, 2018 |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Basic start date:** | May 7, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic finish date:** | May 19, 2018 |
| **Maint. Plan:** | | **Reported By:** | | | |
| **Address:** | 4602 MONROE AVE,SAN DIEGO,CA -92115-3119,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** AMI Special Project-7748

**WO Description: (Long text)**

AMI Special Project-7748

Begin Of Address: 8101224782

4602, MONROE AVE

SAN DIEGO, CA 92115-3119, US

End Of Address

Created from Mobile by BTUCKER on 05/11/2018 11:03:14

AMI ready on arrival. Meter working properly. SN#16502372. Read#0025

Created from Mobile by BTUCKER on 05/11/2018 11:03:14

AMI ready on arrival. Meter working properly. SN#16502372. Read#0025

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101224782 - 4602 MONROE AVE | | |
| **Equipment:** | 1000470206 - 3/4"X7" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643371 | **Notification#:** | 40200209260 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-AMISP - WCM Meters AMI Spe | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Brooke Tucker | | | |
| 0110 | Luis Zavala | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200028240 |
|---|---|---|---|

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000470206 | 3/4"X7" BADGER HR-E DOMESTIC | 8101224782 | 4602 MONROE AVE |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | Mobile status set to STARTED by user BTUCKER on 2018-05-11 09:57:43 for operation 0100<br>Mobile status set to ONSITE by user BTUCKER on 2018-05-11 10:07:40 for operation 0100<br>Mobile status set to COMPLETED by user BTUCKER on 2018-05-11 10:07:41 for operation 0100 |
| 0110 | Verify and possible RPL<br>Mobile status set to STARTED by user LZAVALA on 2018-10-15 11:18:09 for operation 0110<br>Mobile status set to ONSITE by user LZAVALA on 2018-10-15 11:18:13 for operation 0110<br>Mobile status set to COMPLETED by user LZAVALA on 2018-10-15 11:20:25 for operation 0110 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1908877 | D7625-16502372(1) | | HCF | | |

**Comments:**

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200209260 | UC | 4602 MONROE AVE,SAN DIEGO,CA -92115-3119,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000470206 | 8101224782 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X7" BADGER | 4602 MONROE AVE | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643371 | 643371 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 05/07/2018 | 05/30/2018 | | | U17 - WCM Meter Services | UW-AMISP - WCM Meters AMI Special Projects |

**Notification Description (Short Text)**

AMI Special Project-7748

**Room**

**Notification Description (Long Text)**

10/15/2018 11:20:44 PST Luis Zavala (LZAVALA)

complete upon arrival. ami ready meter ok

s/n 16502372 read 0071

37 box in concrete ok

| Problem | Object | Activity | Note |
|---|---|---|---|
| | | | |

**Print Date - Time / User ID User Name**

02/28/2019 - 13:16:50 / DSHOPKINS DAWN HOPKINS

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200209260 | UC | 4602 MONROE AVE,SAN DIEGO,CA -92115-3119,US |

| Problem | Object | Activity | Note |
|---|---|---|---|
| | | | |

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200076684**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | | |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Request Date:** | Feb 20, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic start date:** | Sep 6, 2018 |
| **Maint. Plan:** | | **Reported By:** | | **Basic finish date:** | Sep 18, 2018 |
| **Address:** | 4515 MAX DR,SAN DIEGO,CA -92115-3114,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** RPL WITH 36 POLY LID LONG.

**WO Description: (Long text)**

RPL WITH 36 POLY LID LONG.

03/11/2018 00:35:30 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

RPL WITH 36 POLY LID LONG.

02/20/2018 12:12:55 PST USER RFC_PE5_100 (RFC_PE5_100)

Begin Of Address: 8101223198

4515, MAX DR

SAN DIEGO, CA 92115-3114, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101223198 - 4515 MAX DR | | |
| **Equipment:** | 1000470446 - 3/4"X7" BADGER HR-E DOMESTIC | **Notification#:** | 40200136906 |
| **FSN:** | 643273 | **Cost Center:** | 2000211216 - Meters |
| **MAT:** | MAINTENANCE AND REPAIRS | **Planner Group:** | U17 -WCM Meter Services |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Room:** | |
| **Plant Section:** | 200 | | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200076684 |
|---|---|---|---|

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000470446 | 3/4"X7" BADGER HR-E DOMESTIC | 8101223198 | 4515 MAX DR |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | RPL WITH 36 POLY LID LONG.<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-21 10:32:04 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-21 10:40:58 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-21 10:44:41 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1642851 | D7625-18259834(1) | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200136906 | UC | 4515 MAX DR,SAN DIEGO,CA -92115-3114,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000470446 | 8101223198 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X7" BADGER | 4515 MAX DR | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643273 | 643273 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-BAMI - WCM Meter Boxes for AMI |

**Notification Description (Short Text)**

RPL WITH 36 POLY LID LONG.

**Room**

**Notification Description (Long Text)**

03/11/2018 00:35:30 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

RPL WITH 36 POLY LID LONG.

02/20/2018 12:12:55 PST USER RFC_PE5_100 (RFC_PE5_100)

---

09/21/2018 10:45:59 PST Jonte Cunningham (JLCUNNINGHAM)

36 box with metal lid in concrete needs to be replaced//36 poly lid does

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200136906 | UC | 4515 MAX DR,SAN DIEGO,CA -92115-3114,US |

n't fit

| Problem | Object | Activity | Note |
|---|---|---|---|
| REPL BOX/LID GENERAL | METER BOX - IN DIRT | | |

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200076660**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | | |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Request Date:** | Feb 20, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic start date:** | Sep 6, 2018 |
| **Maint. Plan:** | | **Reported By:** | | **Basic finish date:** | Sep 18, 2018 |
| **Address:** | 4527 MAX DR,SAN DIEGO,CA -92115-3114,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** RPL WITH 36 POLY LID.

**WO Description: (Long text)**

RPL WITH 36 POLY LID.

03/11/2018 01:01:10 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

02/20/2018 11:57:31 PST USER RFC_PE5_100 (RFC_PE5_100)

RPL WITH 36 POLY LID.

Begin Of Address: 8101223819

4527, MAX DR

SAN DIEGO, CA 92115-3114, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101223819 - 4527 MAX DR | | |
| **Equipment:** | 1000466607 - 3/4"X7" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643278 | **Notification#:** | 40200178893 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200076660 |
|---|---|---|---|

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000466607 | 3/4"X7" BADGER HR-E DOMESTIC | 8101223819 | 4527 MAX DR |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | RPL WITH 36 POLY LID.<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-21 09:30:19 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-21 09:36:53 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-21 09:41:31 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1647479 | D7625-17861900(1) | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200178893 | UC | 4527 MAX DR,SAN DIEGO,CA -92115-3114,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000466607 | 8101223819 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X7" BADGER | 4527 MAX DR | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643278 | 643278 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-BAMI - WCM Meter Boxes for AMI |

**Notification Description (Short Text)** — **Room**

RPL WITH 36 POLY LID.

**Notification Description (Long Text)**

03/11/2018 01:01:10 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

02/20/2018 11:57:31 PST USER RFC_PE5_100 (RFC_PE5_100)

RPL WITH 36 POLY LID.

---

09/21/2018 10:46:02 PST Jonte Cunningham (JLCUNNINGHAM)

36 box with metal lid in concrete//36 poly lid doesn't fit// need to rep

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200178893 | UC | 4527 MAX DR,SAN DIEGO,CA -92115-3114,US |

lace box

| Problem | Object | Activity | Note |
|---|---|---|---|
| REPL BOX/LID GENERAL | METER BOX - IN DIRT | | |

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200076638**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | | |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Request Date:** | Feb 20, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic start date:** | Sep 6, 2018 |
| **Maint. Plan:** | | **Reported By:** | | **Basic finish date:** | Sep 18, 2018 |
| **Address:** | 4535 MAX DR,SAN DIEGO,CA -92115-3114,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** RPL WITH 36 POLY LID.

**WO Description: (Long text)**

RPL WITH 36 POLY LID.

03/11/2018 00:40:56 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

RPL WITH 36 POLY LID.

02/20/2018 11:57:32 PST USER RFC_PE5_100 (RFC_PE5_100)

Begin Of Address: 8101223822

4535, MAX DR

SAN DIEGO, CA 92115-3114, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101223822 - 4535 MAX DR | | |
| **Equipment:** | 1000470360 - 3/4"X7" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643279 | **Notification#:** | 40200145947 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200076638 |
|---|---|---|---|

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000470360 | 3/4"X7" BADGER HR-E DOMESTIC | 8101223822 | 4535 MAX DR |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | RPL WITH 36 POLY LID.<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-21 09:08:41 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-21 09:08:43 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-21 09:15:25 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1521184 | D7625-18259998(1) | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200145947 | UC | 4535 MAX DR,SAN DIEGO,CA -92115-3114,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000470360 | 8101223822 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X7" BADGER | 4535 MAX DR | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643279 | 643279 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-BAMI - WCM Meter Boxes for AMI |

**Notification Description (Short Text)**

RPL WITH 36 POLY LID.

**Room**

**Notification Description (Long Text)**

03/11/2018 00:40:56 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

RPL WITH 36 POLY LID.

02/20/2018 11:57:32 PST USER RFC_PE5_100 (RFC_PE5_100)

---

09/21/2018 10:46:05 PST Jonte Cunningham (JLCUNNINGHAM)

36 box with metal lid in concrete// 36 poly lid doesn't fit

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200145947 | UC | 4535 MAX DR,SAN DIEGO,CA -92115-3114,US |

| Problem | Object | Activity | Note |
|---|---|---|---|
| REPL BOX/LID GENERAL | METER BOX - IN DIRT | | |

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200076721**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | **Request Date:** | Feb 28, 2018 |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Basic start date:** | Sep 6, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic finish date:** | Sep 18, 2018 |
| **Maint. Plan:** | | **Reported By:** | | | |
| **Address:** | 4620 MAX DR,SAN DIEGO,CA -92115-3115,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** REPLACE METER LID

**WO Description: (Long text)**

REPLACE METER LID

Begin Of Address: 8101223866

4620, MAX DR

SAN DIEGO, CA 92115-3115, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101223866 - 4620 MAX DR | | |
| **Equipment:** | 1000471155 - 3/4"X9" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643290 | **Notification#:** | 40200146203 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

**Object List:**

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200076721 |
|---|---|---|---|

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000471155 | 3/4"X9" BADGER HR-E DOMESTIC | 8101223866 | 4620 MAX DR |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | REPLACE METER LID<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-21 12:36:30 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-21 12:42:33 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-21 12:45:05 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1904888 | D5725-17130154(1) | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200146203 | UC | 4620 MAX DR,SAN DIEGO,CA -92115-3115,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000471155 | 8101223866 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X9" BADGER | 4620 MAX DR | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643290 | 643290 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-BAMI - WCM Meter Boxes for AMI |

**Notification Description (Short Text)**

REPLACE METER LID

**Room**

**Notification Description (Long Text)**

09/21/2018 14:16:22 PST Jonte Cunningham (JLCUNNINGHAM)

36 poly lid didn't fit on 36 concrete box//36 box in concrete needs to b

e replaced

| Problem | Object | Activity | Note |
|---|---|---|---|
| REPL BOX/LID GENERAL | METER BOX - IN DIRT | | |

**Print Date - Time / User ID User Name**

02/28/2019 - 13:24:58 / DSHOPKINS DAWN HOPKINS

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200083417**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | | |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Request Date:** | Aug 28, 2017 |
| **Task List:** | E | **Assigned To:** | | **Basic start date:** | Sep 7, 2018 |
| **Maint. Plan:** | | **Reported By:** | | **Basic finish date:** | Sep 19, 2018 |
| **Address:** | 4641 MAX DR,SAN DIEGO,CA -92115-3116,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** PER GET IT DONE APP; REPLACE BROKEN MTR

**WO Description: (Long text)**

PER GET IT DONE APP; REPLACE BROKEN MTR

03/11/2018 00:54:56 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

PER GET IT DONE APP; REPLACE BROKEN MTR

08/28/2017 08:12:36 PST USER RFC_PE5_100 (RFC_PE5_100)

Begin Of Address: 8101223884

4641, MAX DR

SAN DIEGO, CA 92115-3116, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101223884 - 4641 MAX DR | | |
| **Equipment:** | 1000406208 - 3/4"X7" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643295 | **Notification#:** | 40200168139 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200083417 |
|---|---|---|---|

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000406208 | 3/4"X7" BADGER HR-E DOMESTIC | 8101223884 | 4641 MAX DR |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | PER GET IT DONE APP; REPLACE BROKEN MTR<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-22 10:31:41 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-22 10:38:55 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-22 10:41:15 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1877223 | D7625-16033707 | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200168139 | UC | 4641 MAX DR,SAN DIEGO,CA -92115-3116,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000406208 | 8101223884 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 3/4"X7" BADGER | 4641 MAX DR | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643295 | 643295 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-MBX - WCM Meter Boxes and Lids #2002 |

**Notification Description (Short Text)**

PER GET IT DONE APP; REPLACE BROKEN MTR

**Room**

**Notification Description (Long Text)**

03/11/2018 00:54:56 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

PER GET IT DONE APP; REPLACE BROKEN MTR

08/28/2017 08:12:36 PST USER RFC_PE5_100 (RFC_PE5_100)

---

09/22/2018 11:40:48 PST Jonte Cunningham (JLCUNNINGHAM)

done upon arrival//36 box in concrete in good condition

**Print Date - Time / User ID User Name**

02/28/2019 - 13:26:10 / DSHOPKINS DAWN HOPKINS

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200168139 | UC | 4641 MAX DR,SAN DIEGO,CA -92115-3116,US |

| Problem | Object | Activity | Note |
|---|---|---|---|
| NO PROBLEM FOUND | METER BOX - IN DIRT | | |

# MAINTENANCE WORK ORDER
ORIGINAL

**Work Order #**
**20200083314**

| | | | | | |
|---|---|---|---|---|---|
| **WO Type:** | UCOR | **WO Status:** | REL MANC MOBI NMAT PRC SETC/CMPL | | |
| **Priority:** | Medium (1-30 Days) | **Criticality:** | | **Request Date:** | Feb 26, 2018 |
| **Task List:** | E | **Assigned To:** | | **Basic start date:** | Sep 7, 2018 |
| **Maint. Plan:** | | **Reported By:** | | **Basic finish date:** | Sep 19, 2018 |
| **Address:** | 4479 MENLO AVE,SAN DIEGO,CA -92115-4445,US | **Contact Person:** | | **Contact Phone:** | |

**WO Description:** REPLACE BROKEN CONCRETE P6.

**WO Description: (Long text)**

REPLACE BROKEN CONCRETE P6.

03/11/2018 00:35:39 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

02/26/2018 15:42:43 PST USER RFC_PE5_100 (RFC_PE5_100)

REPLACE BROKEN CONCRETE P6.

Begin Of Address: 8101224648

4479, MENLO AVE

SAN DIEGO, CA 92115-4445, US

End Of Address

| | | | |
|---|---|---|---|
| **FLoc.:** | 8101224648 - 4479 MENLO AVE | | |
| **Equipment:** | 1000469831 - 1 1/2" BADGER HR-E DOMESTIC | | |
| **FSN:** | 643338 | **Notification#:** | 40200137065 |
| **MAT:** | MAINTENANCE AND REPAIRS | **Cost Center:** | 2000211216 - Meters |
| **Work Center:** | UW-MBXRP - WCM Meter Boxes an | **Planner Group:** | U17 -WCM Meter Services |
| **Plant Section:** | 200 | **Room:** | |
| **EQ Manufacture Serial No:** | | | |

**Labor Assignment:**

| Op. No. | Technician | Technician | Technician | Technician |
|---|---|---|---|---|
| 0100 | Jonte Cunningham | | | |

**Unplanned Materials:**

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin / PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |

| | | MAINTENANCE WORK ORDER<br>ORIGINAL | Work Order #<br>20200083314 |
|---|---|---|---|

| Op. No. | Material No. | Description | Unit | Item Cat. | SLoc / SBin<br>PR/ PO / Vend. | Quan. Reqd. | Issues/ Recd. |
|---|---|---|---|---|---|---|---|
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

**Object List:**

| Asset | Description | FLoc | Description |
|---|---|---|---|
| 1000469831 | 1 1/2" BADGER HR-E DOMESTIC | 8101224648 | 4479 MENLO AVE |

**Operations:**

| Op. No. | Details |
|---|---|
| 0100 | REPLACE BROKEN CONCRETE P6.<br>Mobile status set to STARTED by user JLCUNNINGHAM on 2018-09-22 10:02:37 for operation 0100<br>Mobile status set to ONSITE by user JLCUNNINGHAM on 2018-09-22 10:09:16 for operation 0100<br>Mobile status set to COMPLETED by user JLCUNNINGHAM on 2018-09-22 10:12:06 for operation 0100 |

**Measurement Readings:**

| Meas. Point | Description | Value | Unit | Date | Time |
|---|---|---|---|---|---|
| 1530574 | D5925-17079181(1) | | HCF | | |

**Comments:**

**Technician Signatures:**

| Name | Hours | Sign | Date |
|---|---|---|---|
| | | | |

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200137065 | UC | 4479 MENLO AVE,SAN DIEGO,CA -92115-4445,US |

| System Status | User Status |
|---|---|
| NOPR ORAS | CRTD |

| Equipment No. | Functional Location |
|---|---|
| 1000469831 | 8101224648 |

| Equipment Description | Functional Location Description | Priority |
|---|---|---|
| 1 1/2" BADGER H | 4479 MENLO AVE | Medium (1-30 Days) |

| Old Asset number (Equipment) | Old Asset number (Functional Location ) | Location | Plant Section |
|---|---|---|---|
| 643338 | 643338 | | 200 - WATER |

| Start Date | End Date | Reported by | Person Resp. | Planner Group | Work Center |
|---|---|---|---|---|---|
| 03/12/2018 | 04/10/2018 | | | U17 - WCM Meter Services | UW-BAMI - WCM Meter Boxes for AMI |

**Notification Description (Short Text)**

REPLACE BROKEN CONCRETE P6.

**Room**

**Notification Description (Long Text)**

03/11/2018 00:35:39 PST . IAMSD Firefighter IT Support User (IAMSDIT_..

02/26/2018 15:42:43 PST USER RFC_PE5_100 (RFC_PE5_100)

REPLACE BROKEN CONCRETE P6.

---

09/22/2018 10:13:29 PST Jonte Cunningham (JLCUNNINGHAM)

p6 box in concrete needs to be replace

# Notification Shop Paper

- Original -

| Notification no. | Notification Type | Address |
|---|---|---|
| 40200137065 | UC | 4479 MENLO AVE,SAN DIEGO,CA -92115-4445,US |

| Problem | Object | Activity | Note |
|---|---|---|---|
| REPL BOX/LID/ISRT #6 | METER BOX - IN DIRT | | |

CITY OF SAN DIEGO


**Project Information Details**
**District 3 Block 3-HH UUD**

## General Information

| | |
|---|---|
| **Project Identification Number:** | B00837 (Utility Undergrounding Asset) |
| **Project Description:** The project will install street lights within Block 3HH (Talmadge 3) for the Utilities Undergrounding Program. | |
| **Contact Person:** | Romaya, Nibras |
| **Council District(s):** | 9 |
| **Community Area(s):** | Mid-City:Kensington-Talmadge |

## Estimated Project Schedule[1]

If timeline does not show, please click here for instructions on how to resolve this.




## Estimated Project Dollar Amounts[1]

| | |
|---|---|
| **A. Total Project Cost:[1]** | $1,028,845 |
| **B. Project Allocated Budget to This Date[1]** | $1,353,845 |
| **C. Total Expended Amount to Date:[1]** | $1,343,671 |

## Construction Activity

| | |
|---|---|
| **A. Estimated Construction Contract Amount: [1]** | $874,518 |
| **B. Funding Status:[3]** | Fully Funded |
| **C. Contractor:** | HMS Construction, Inc. |
| **D. Expected Contract Duration:[1]** | 6 Months |

## Additional Remarks

None

Form PWD1502

Updated As Of: 02/01/2019

**Project Information Details**
## Block 3HH (Talmadge 3) Rd Imp UU352

### General Information


| | |
|---|---|
| **Project Identification Number:** | B17068 (Utility Undergrounding Asset) |

**Project Description:** This project consists of curb ramp installations, street resurfacing (overlay and/or slurry seal), and other work as pertinent and necessary to the construction of the Block 3HH (Talmadge 3) Underground Utility Road Improvements Project UU352.

| | |
|---|---|
| **Contact Person:** | Zhang, Dayue |
| **Council District(s):** | 9 |
| **Community Area(s):** | Mid-City:Kensington-Talmadge |

### Estimated Project Schedule[1]

If timeline does not show, please click here for instructions on how to resolve this.




### Estimated Project Dollar Amounts[1]

| | |
|---|---|
| **A. Total Project Cost:[1]** | $1,368,257 |
| **B. Project Allocated Budget to This Date[1]** | $1,553,257 |
| **C. Total Expended Amount to Date:[1]** | $112,095 |

### Construction Activity

| | |
|---|---|
| **A. Estimated Construction Contract Amount: [1]** | $1,000,306 |
| **B. Funding Status:[3]** | Fully Funded |
| **C. Contractor:** | To Be Selected |
| **D. Expected Contract Duration:[1]** | 9 Months |

### Additional Remarks

None

Form PWD1502

Updated As Of: 02/01/2019